



Diamond Shamrock

US EPA RECORDS CENTER REGION 5



460342

Gulf Coast Area

June 5, 1981

U.S. Environmental Protection Agency
Region 5
Sites Notification
Chicago, Illinois 60604

RE: Notification of Hazardous Waste Site
Cincinnati Plant
Cincinnati, Ohio

Dear Sir:

In compliance with Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, enclosed please find a completed "Notification of Hazardous Waste Site" form for the Diamond Shamrock Corporation Cincinnati site.

I trust that this notification is satisfactory. If you should have any questions, please contact me at (713) 476-1250.

Sincerely,

L. R. Heble, P.E.
Environmental Services Manager

JS/LRH/gg
Enclosure

JUN 11 1981



Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

OH #147

810608

OH5-000-001-073

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Diamond Shamrock Corporation
Street 717 N. Harwood St.
City Dallas State TX. Zip Code 75201

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Diamond Shamrock Corp-
Cincinnati Silicate Plant
Street 4701 Paddock Road
City Cincinnati County Hamilton State OH Zip Code 45229

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Heble, LaVern - Env. Services Manager
Phone 713/476-1250

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1920 To (Year) 1977

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☐ Inorganics
3. ☒ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☒ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000307 JUN -81

JUN 11 1981

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 150

gallons _____

Total Facility Area

square feet _____

acres <0.1

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Peter Piekenbrock

Street 351 Phelps Court

City Irving

State TX

Zip Code 75061

Signature

Peter Piekenbrock

Date

5/29/81

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other

1981 INDUSTRIAL WASTE SURVEY

A. Company Information

1. Company Name: Diamond Shamrock Corporation
2. Company Address: 4701 Paddock Road
Cincinnati, Ohio 45229
3. County in which company located: Hamilton
4. Name of person responding to survey: David T. Wingfield Telephone: 513-242-2900

B. Description of wastes currently produced:

<u>Waste name</u>	<u>quantity generated</u>	<u>solid, sludge liquid, hazardous</u>	<u>on-or off-site disposal</u>	<u>method (pit, incinerator, landfill, etc.)</u>
1. Sand	80 T/yr	Solid	Off	Landfill
2. Sodium Carbonate	60 T/yr	Solid	Off	Landfill
3. Bricks	60 T/yr	Solid	Off	Landfill
4. Paper/Wood/Rubbish	20 T/yr	Solid	Off	Landfill

C. Off-site: Give haulers name and address, and site of ultimate disposal, for each of the above listed wastes.

- | | |
|---|---|
| 1-3 - Hauler: Newberry Const. Co.
10080 Winschield Rd.
West Chester, Ohio 45069 | 4 - Hauler: Rumpke Container
10795 Hughes Rd.
Cinti, Ohio 45247 |
| Site: ELDA, 5701 Este Ave., Cinti, Ohio 45232 | Site: Unknown |

D. Closed sites: Give waste descriptions and approximate quantities for any wastes previously disposed in a now closed or inactive on-site facility. Give dates site used and closed.

1920-1977

Sand	Resins
Sodium Carbonate	Carbon Tetrachloride *
Bricks	Oil and Sludges
Sodium Hydroxide *	Salts
Halogenated Aliphatics *	Asbestos
Paint Wastes	Trichloroethylene *

E. If you were unable to answer any above questions because the information is considered confidential by your company, indicate this here and we will contact you personally.

* The total quantity of these wastes disposed of onsite is estimated at 150 cubic feet.